



Oil-fired condensing boilers OSCR 18 – 24 – 30 OSCR 45

Appliances temporarily delivered without cleaning brush


JS

N° ITOE0247-en


06/10/2021

1. Purpose

- The following appliances are temporarily delivered without the **round cleaning brush** reference **300024571**, due to a worldwide raw material shortage. This brush is designed to clean the combustion chamber.



- Appliances delivered without the brush are marked with the following label :




2. Appliances concerned

| Appliances concerned | Reference | Description | Package |
|----------------------|-----------|-------------|---------|
| OSCR 18 - 24 - 30 | 100017739 | OSCR 18 | MV12 |
| | 100017740 | OSCR 24 | MV13 |
| | 100017741 | OSCR 30 | MV14 |
| | 100019265 | OSCR 18 LS | MV19 |
| | 100019266 | OSCR 24 LS | MV20 |
| | 100019268 | OSCR 30 LS | MV21 |
| OSCR 45 | 7660318 | OSCR 45 | MV104 |

3. Require the brush to be sent to you

1. Note the serial number of your appliance on the nameplate:




2. Send :
 - your address
 - your appliance serial number

to the following e-mail adress :

piecederechange@oertli.fr

3. The brush will be sent to you free of charge, **as soon as it is available in stock.**

| Appliances concerned | Description | Spare part reference | |
|-----------------------------------|---|----------------------|----------------------|
| OSCR 18 – 24 – 30 – 45 |  | 300024571 | ROUND CLEANING BRUSH |